

List of Materials to be covered under Service Contract for Canyon State Academy (R.O.P.)

Qty	Part Number	Description of Hardware
20	SAF10598	IR Adrsbl Source Controller W/Multiplexer
5	SAF10590	12-volt Power Supply for up to 8 Source Controllers
1	SAF10566	96x96 Routing Switch
1	SAF10584	X/Y Routing Switch Control Panel
6	SAF10568	6.5 MHz Audio/Video Multiplexer Rack Mount
3	SAF10569	6.5 MHz Coax Receiver Rack Mount
30	SAF10583	Twisted Pair Dual Transmitter
30	SAF10573	6.5 MHz Twisted Pair Remux Rack Mount
4	SAF10579	Frame 14-Card Slot w/Power Supply
1	SAF10042	1U Rack Mount Supermicro Server w/Windows 2000
1	SAF10949	Pathway Version 5 Series Software 144 User

To be included in the service contract is tech support calling, as well as if needed on site troubleshooting and installation of any retuned serviced or replaced Safari product listed above